

Stator Voltage
Static Voltage is 1.25V, Full Battery Voltage when Charging
Indicator Light
Stator Voltage
Battery
N
BAT
This Unit is Fully Insulated. Ground must be Applied to one of these Studs.